

Operator Qualification Program

- Operators should have their written OQ Plan prepared by April 27, 2001.
- Operators had until October 28, 2002, to be in compliance with the implementation of the OQ Plan, to qualified all individuals performing CT.
- ◆ CSFM had until December 2005 to inspect all Operator Qualification Programs.



OQP Cont.

- ♦ At the end of 2005, the situation was as follows:
 - 43 Operators are under CSFM Jurisdiction, all were inspected by end of December 2005, eider by CSFM, DOT or jointly.



♦ Following Up Inspection after Dec 2005:

- CSFM is following up with Plan and Program Inspection for all intrastate Operators.
- CSFM is performing Field Inspection for all intrastate and interstate Operators.



- ◆ The Follow up Plan and Program Inspection will focus on the:
 - Compliance of the OQ Plan with Title 49,
 Part 195, Subpart G, including,
 Implementation of the OQ Plan:
 - Correcting all the non-compliance issues noted in the Plan and Program during previous inspection,
 - Inspection of the Qualification Records of all persons performing Covered Tasks including appropriateness of the methods used to evaluate them during qualification process.



- Where we are this point in time with the OQ Plan and Program Follow Up?
 - CSFM is following up with Plan and Program Inspection for all 21 intrastate Operators.
 - 19 Operator's Plans and Programs were followed up already (3 more to go)
 - 15 out of 19 Operator are in compliance with the OQ Rule.



- Where we are this point in time with the OQ Field Inspections?
 - CSFM is performing Field Inspection for all
 43 intrastate and interstate Operators.
 - 13 Operators were OQ Field Inspected until now, there are 30 more to go



Follow up: Cont.

- The OQ Field inspection will be performed following DOT OQ Protocol 9 Check List.
- ♦ The OQ Field inspection will be addressing at least the followings:
 - Identification of the person performing covered task
 - Identification of the covered task performed
 - Verification of person's qualification
 - Verification if procedure is present
 - Verification of individual's AOC knowledge
 - Verification of span of control for non-OQ



Summary Statistics: CA Intrastate

OQ Plan and Program Violation Summary Statistics

- Violation of 195.505(a), 4 of 21 operator did not identified all applicable covered tasks
- **♦** Violation of 195.505(b),
 - 5 of 21 operators did not qualified their employees
 - 5 of 21 operators did not include AOC in the evaluation process
 - 1 of 21 operator dose not have provision for contractor and other entity
 - 1 of 21 operators plan ask for oral and job performance evaluation methods, and the operator used oral only, violating their own OQ Plan.



Summary Statistics: Cont.

- **♦** Violation of 195.507(a) and (b),
 - 2 of 21 operator has no evaluation method on the OQ records of qualification.
 - 1 of 21 operator has no dates of evaluation on the qualification records
 - 1 of 21 operator has no contractors OQ record.
- ♦ Violation of 195.509(b), 1 of 21 do not have records of transactional qualification in 2002.



Summary Statistics: CA

OQ Field Violation Summary Statistics

- ♦ Violation of 195.402(a), 1 of 13 operator has no procedure available during field inspection for OQ covered task performed.
- ♦ Violation of 195.505(a), 2 of 13 operators do not have the performed CT on their list.
- ♦ Violation of 195.505(c), 1 of 13 operators do not have task specific span of control
- Violation of 195.505(b), 2 of 13 operators has use not OQ personnel to perform critical CT with zero span of control
- Violation of 195.507, 1 of 13 operators has no OQ records for the contractor's personnel.



Contractors Issues

- **♦** CSFM does not have jurisdiction over the contractors.
- ◆ The qualification contractor personnel must be addressed in the operator's qualification plan, including qualification of personnel working under a mutual aid agreement.
- If the operator relies on a contractor's or thirdparty plan, it is the operator's responsibility to demonstrate that the plan(s) meet all the requirements of this subpart.



Conclusive Word

- If you have any questions regarding the OQ requirements, please call us at:
 - Telephone Number for CSFM Office in Lakewood is (562) 497-9100
 - Pipeline Safety Supervisor name is Chuck MacDonald
 - Pipeline Safety Engineer: Adriana Crasnean, PE.
- We are wishing you to be in COMPLIANCE all the time.